

Surface Mount


To + VDC (fuse @ 2A):**RED**

To Chassis Ground:**BLACK**

For Low Power: **WHITE**
Apply +VDC to **WHITE** wire.

For Synchronization**YELLOW**

Connect **YELLOW** wires of multiple lighthead together for synchronization
(All heads should be set at the same Flash Pattern)



For Simultaneous or Alternating Flash:

1. Apply +VDC to **RED** and **YELLOW** wires simultaneously to enter Grouping mode;
lighthead will display short (single or double) flash:
 - Single flash = Group1
 - Double flash = Group2
2. Remove **YELLOW** wire from +VDC then momentarily apply +VDC to change Groups:
 - Heads of the same Group will flash together.
 - Heads of the different Group will flash alternately.

For Flash Patterns:

Momentarily apply +VDC to **YELLOW** wire:

- once for next pattern
- quick three times for pattern 1

NOTE: This unit may not be factory set at FP# 1.

FP#	Flash Patterns
1	Single (R65)
2	Double (R65)
3	Triple (R65)
4	Quad (2Hz)
5	Steady